







Ordering spares / Ersatzteil - Regelung / Pièces de rechange / Parti di ricambio / Lista de recambios / Onderdelen bestellen (NL/B) / Κωδικοί Ανταλλακτικών / Bestilling af reservedele / Beställning av reservdelar / Bestilling av reservedeler / Резервни части / Запчасти / Części zapasowe / Piese de schimb / Rendelhető alkatrészek / Запасні частини / Резервни делови / Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezerves daļas / Náhradní díly / Náhradné diely / Yedek parça siparişi / Nadomestni deli

- XX = AA, AD,
- 1 - B 961973 XX
 - 2 - B 961951 NU
 - 3 - B 961974 XX
 - 4 - B 961916 NU
 - 5 - A 861399 NU
 - 6 - B 961975 NU
 - 7 - B 961917 XX
 - 8 - A 962574 NU
 - 9 - B 960255 NU
 - 10 - B 961705 XX



 P	bar	 MAX. 10 0,5	 5 1 	Q (3 bar) 
 T	°C	 MAX. 80	 65 40 	l/min 3,8



1




2



3

4


5








3

4

5





6



1

2



P	T	°C	4	3	2	1	0
			°C	°C	°C	°C	°C
0,3 MPa 3 bar	50°C	15°C	27	33	41	48	50
	65°C	15°C	33	42	53	63	65
	85°C	15°C	41	53	68	83	85

